

CITY OF BALTIMORE WET WEATHER CONSENT DECREE SMOKE AND DYED WATER TESTING FORM

Page 1 of 4

Sewershed: JONES FALLS

Company: REI/DRAYCO

Date: 07/16/2008

Test to be Performed: SMOKE

Ground Condition: DRY


Supervisor: ER

Manhole ID: S31SS_042MH

Test ID: 0994-388

Notifications
Made: X
(Residents, Fire, 311)

Field Sketch: (Show All Manholes with Numbers, Blower Placement Location, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photograph Numbers)



TOTAL: 903.1 LF

[illegible]

CITY OF BALTIMORE
SMOKE TESTING OBSERVATION SUMMARY
JONES FALLS SEWERSHED
BALTIMORE CITY PROJECT 994
REI/DRAYCO

Unique Test ID: 388	Date: 07/16/2008	Basin: JF-19
Defect No: OB01-01	Supervisor: E.R.	Dye Test Recommended: N
Address: 402 W. 29TH ST.		
Source Type: 16	Location: 08	Severity: 03
Sector: 02	Drainage Area: 4	
Comments: SMOKE IS COMING FROM UNDETERMINED DEFECT IN BACKYARD NEAR WALL		

SMOKE TEST PHOTOGRAPHS



Photograph No: OB01-01
Filename: 0994-388_OB01-01.jpg

**CITY OF BALTIMORE
SMOKE TESTING OBSERVATION SUMMARY
JONES FALLS SEWERSHED
BALTIMORE CITY PROJECT 994
REI/DRAYCO**

Unique Test ID: 388	Date: 07/16/2008	Basin: JF-19
Defect No: OB02-01	Supervisor: E.R.	Dye Test Recommended: N
Address: 2900 MILES AVE.		
Source Type: 16	Location: 08	Severity: 03
Sector: 02	Drainage Area: 5	
Comments: SMOKE IS COMING FROM THE BEHIND THE BASE OF THE FENCE - UNDETERMINED DEFECT		

SMOKE TEST PHOTOGRAPHS



Photograph No: OB02-01
Filename: 0994-388_OB02-01.jpg